



SKU:

FORTE SOVEREIGN PLUS MATTRESS (ILS)

\$1,499.99 <u>\$1,499.99</u>

The Forte Sovereign Plus Mattress is a medium-risk static support surface. Made in Australia, it combines visco-elastic immersion with zoned comfort and a durable cover for use across home, hospital and aged care environments.



Scan QR code to view product online



VARIATIONS





PRODUCT DESCRIPTION

The Sovereign Plus Mattress is engineered to provide effective support and comfort for those at medium risk of pressure injury. Its visco-elastic upper layer conforms to pressure points, while the dual-density secondary layer enhances immersion and envelopment.

Profiled stabilising sides assist with positioning and bed conformity. A firm base provides sacral support and assists with repositioning.

The moisture-resistant Premiflex cover is stretchable, anti-shearing and easy to clean – making it suitable for high-demand settings.

Who it's for

- For clients with medium pressure injury risk who need enhanced support and hygiene.
- For therapists requiring a durable, clinically supportive mattress with versatile use across facilities or at home.

Key features

- **Visco-elastic support surface** sensitive immersion interface, dual density secondary immersion support layer, zoned for optimal immersion and comfort
- **Profiled stabilising sides** enables ease of primary patient care, facilitates patient transfers, unique hinge points allow the mattress to easily conform to varied bed positions, encourages central patient positioning
- Firm base support layer provides sacral protection and exceptional comfort and support for repositioning and patient care
- **Sloped heel relief** enhanced pressure redistribution and protection for critical at-risk heel region
- Premiflex cover superior infection control, hygiene and high-performance cover that is suitable for demanding care settings. Produced in Belgium, the cover is a 4-way stretch PU interface which is moisture vapour permeable and anti-shearing. Heavy-duty upgraded PVC base material protects premature cover deterioration

